

Case-studies in plastering and rendering mortars. Sampling and testing for salts

Teresa Diaz Gonçalves

Case-studies in plastering and rendering mortars. Sampling and testing for salts

Lecture contents

- Four case studies in Portugal (indicated by IPPAR + DGMN)
 - Methodology
 - Salvas church, Sines
 - Alhos Vedros tide-mill
 - House of Despacho, Pereira, Coimbra
 - Santa Clara-a-Nova Monastery, Coimbra
- Inspection form

Methodology for assessment and diagnosis of damage

Diagnoses are rarely based on 100% certainty:

- complexity of the problems
- financial restrictions (normal...) => limitations in the number and type of analyses

Methodology for assessment and diagnosis of damage

- Site-inspections
- Sampling / testing

Methodology for assessment and diagnosis of damage

- Site-inspections
- Sampling / testing
 - Moisture and salt distribution evaluated in selected walls


Methodology for assessment and diagnosis of damage

- Site-inspections
- Sampling / testing
 - **Moisture and salt distribution evaluated in selected walls**
 - Samples collected by powder-drilling
 - 16 or 20 mm rotary drills





Methodology for assessment and diagnosis of damage

- Site-inspections
- Sampling / testing
 - **Moisture and salt distribution evaluated in selected walls**
 - Samples collected by powder-drilling
 - 16 or 20 mm rotary drills
 - Several heights and depths





Methodology for assessment and diagnosis of damage

- Site-inspections
- Sampling / testing
 - **Moisture and salt distribution evaluated in selected walls**
 - Samples collected by powder-drilling
 - 16 or 20 mm rotary drills
 - Several heights and depths
 - MC => mass loss after oven drying at 105°C
 - HMC => mass increase at 20°C and 96% RH



Methodology for assessment and diagnosis of damage

- Site-inspections
- Sampling / testing
 - **Moisture and salt distribution evaluated in selected walls**
 - Samples collected by powder-drilling
 - 16 or 20 mm rotary drills
 - Several heights and depths
 - **MC => mass loss after oven drying at 105°C**
 - **HMC => mass increase at 20°C and 95% RH**



Methodology for assessment and diagnosis of damage

- Site-inspections
- Sampling / testing
 - **Moisture and salt distribution evaluated in selected walls**
 - Samples collected by powder-drilling
 - 16 or 20 mm rotary drills
 - Several heights and depths
 - MC => mass loss after oven drying at 105°C
 - HMC => mass increase at 20°C and 96% RH
 - **Soluble salts investigated by means of:**
 - Ion chromatography
 - XRD / EDS

Methodology for assessment and diagnosis of damage

- Site-inspections
- Sampling / testing
 - **Moisture and salt distribution evaluated in selected walls**
 - Samples collected by powder-drilling
 - 16 or 20 mm rotary drills
 - Several heights and depths
 - MC => mass loss after oven drying at 105°C
 - HMC => mass increase at 20°C and 96% RH
 - **Soluble salts investigated by means of:**
 - Ion chromatography => Na⁺, K⁺, Mg²⁺, Cl⁻, NO₃⁻, SO₄²⁻
 - XRD / EDS
 - XRD => mineralogical composition (content ≥ 2 to 4% W)
 - EDS (energy-dispersive X-ray spectroscopy) => semiquantitative info about content
 - on efflorescence, when it was visible
 - on the fine fraction, after elimination of material retained on 106 μm sieve

1 - Salvas Church, Sines

1 - Salvos Church, Sines



SW (front) façade

- Built 1529 by Portuguese navigator Vasco da Gama (to thank the success of his trip to discover the sea route to India)
- Façade dates from XVIII century
- 1997 => lime render (small percentage of cement) + lime-wash

Damage (2004):

- cracking, sanding of the render, erosion
- 60% of the surface damaged
- reached more than 4 m height
- mainly at the walls middle height




1 - Salvos Church, Sines



SW (front) façade

- Next to Sines harbour
lateral SE façade faces Sines
harbour (150 km south of Lisbon)
- Next to water fountain



Water fountain
and reservoir

1 - Salvas Church, Sines

damage seems to start at the cracks ...



November 2003

← 4.0 m

← 3.0 m


← 2.0 m

← 1.0 m


← 0.5 m

← 0.2 m

NE (rear) façade







November 2003



NE (rear) façade


Salvas - Back façade






- MC => rising damp seems very significant:
 - at the base of the wall, the MC is very high (and much higher than the HMC)
 - MC decreases with the distance to the pavement
- HMC => the stronger accumulation of salt occurs at around 2m from the pavement
 - close to the ground the moisture content is very high => stage I conditions => efflorescence (washed out ...)

November 2003




NE (rear) façade

In-depth analysis at the lower drilling hole
(0.2 m from the pavement)




November 2003




In-depth analysis at the lower drilling hole (0.2 m from the pavement):

- both the MC and the HMC are constant inside the wall
- the MC is high and much higher than the HMC

Features characteristic of rising damp...



November 2003



XDR/EDS on the fine fraction
(3 mm thick sample)

Halite (NaCl)	+ / ++
Calcite, CaCO ₃	+++
Quartz, SiO ₂	++
Feldspars	vtg / +
Mica	vtg

Ion content of samples 0-2cm


Height (m)	Na ⁺	K ⁺	Mg ²⁺	Cl ⁻	NO ₃ ⁻	SO ₄ ²⁻
3.0	0.33	0.07	nd	0.60	0.33	0.08
0.5	0.05	0.04	nd	0.16	0.04	0.09

WTA classification for anion content (WTA 1991):

low content, medium content, high content

- DRX/EDS => halite (sea water ... marine fog ...)
- IC => chloride (sea) + some nitrate (ground)

November 2003



XDR/EDS on the fine fraction
(3 mm thick sample)

Halite (NaCl)	+ / ++
Calcite, CaCO ₃	+++
Quartz, SiO ₂	++
Feldspars	vtg / +
Mica	vtg

Ion content of samples 0-2cm

Height (m)	Na ⁺	K ⁺	Mg ²⁺	Cl ⁻	NO ₃ ⁻	SO ₄ ²⁻
3.0	0.33	0.07	nd	0.60	0.33	0.08
0.5	0.05	0.04	nd	0.16	0.04	0.09

WTA classification for anion content (WTA 1991):
 low content, medium content, high content

- DRX/EDS => halite (sea water ... marine fog ...)
- IC => chloride (sea) + some nitrate (ground)

November 2003



XDR/EDS on the fine fraction
(3 mm thick sample)

Halite (NaCl)	+ / ++
Calcite, CaCO ₃	+++
Quartz, SiO ₂	++
Feldspars	vtg / +
Mica	vtg

November 2003



XDR/EDS on the fine fraction
(3 mm thick sample)

Halite (NaCl)	+ / ++
Calcite, CaCO ₃	+++
Quartz, SiO ₂	++
Feldspars	vtg / +
Mica	vtg

November 2003



XDR/EDS on the fine fraction
(3 mm thick sample)


Halite (NaCl)	+ / ++
Calcite, CaCO ₃	+++
Quartz, SiO ₂	++
Feldspars	vtg / +
Mica	vtg

Ion content of samples 0-2cm

Height (m)	Na ⁺	K ⁺	Mg ²⁺	Cl ⁻	NO ₃ ⁻	SO ₄ ²⁻
3.0	0.33	0.07	nd	0.60	0.33	0.08
0.5	0.05	0.04	nd	0.16	0.04	0.09

WTA classification for anion content (WTA 1991):
low content, medium content, high content

November 2003



XDR/EDS on the fine fraction
(3 mm thick sample)


Halite (NaCl)	+ / ++
Calcite, CaCO ₃	+++
Quartz, SiO ₂	++
Feldspars	vtg / +
Mica	vtg

Ion content of samples 0-2cm

Height (m)	Na ⁺	K ⁺	Mg ²⁺	Cl ⁻	NO ₃ ⁻	SO ₄ ²⁻
3.0	0.33	0.07	nd	0.60	0.33	0.08
0.5	0.05	0.04	nd	0.16	0.04	0.09

WTA classification for anion content (WTA 1991):
low content, medium content, high content

November 2003



XDR/EDS on the fine fraction
(3 mm thick sample)

Halite (NaCl)	+ / ++
Calcite, CaCO ₃	+++
Quartz, SiO ₂	++
Feldspars	vtg / +
Mica	vtg

Ion content of samples 0-2cm

Height (m)	Na ⁺	K ⁺	Mg ²⁺	Cl ⁻	NO ₃ ⁻	SO ₄ ²⁻
3.0	0.33	0.07	nd	0.60	0.33	0.08
0.5	0.05	0.04	nd	0.16	0.04	0.09

WTA classification for anion content (WTA 1991):

low content, medium content, high content

- DRX/EDS => halite (sea water ... marine fog ...)
- IC => chloride (sea) + some nitrate (ground)

1 - Salvas Church, Sines

Conclusions

- Rising damp is very significant
- Salts: chloride (sea) + some nitrate (ground)

Key recommendations

- Prevent the ingress of chloride => hardly feasible ...
=> **Prevent rising damp** (prevents also the access of the nitrate):
 - investigate possible contribution of the old fountain
 - damp proof course ?
- Use a plaster that allows drying of the wall (salt transporting)
- Use a paint with good adherence (some surface decay is still expected) ... silicate?

2 - Alhos-Vedros tide-mill

2 - Alhos-Vedros tide-mill



NW (front) façade

situated between the kettle (artificial lake meant to accumulate water during the high tide) and the river branch

2 - Alhos-Vedros tide-mill

History

- built beginning of the XVIII century
- inactive since 1940, will work as a museum



NW (front) façade

situated between the kettle (artificial lake meant to accumulate water during the high tide) and the river branch



NW (front) façade

2 - Alhos-Vedros tide-mill

History

- built beginning of the XVIII century
- inactive since 1940, will work as a museum

Situation

- inside a branch of the Tagus estuary
- less than 10 km from the open sea



2 - Alhos-Vedros tide-mill

History

- built beginning of the XVIII century
- inactive since 1940, will work as a museum

Situation

- inside a branch of the Tagus estuary
- less than 10 km from the open sea

Materials (1999):

- plasters were replaced up to:
 - 2.6m in the NW wall
 - 1.4m in the SW wall
 - 1.0m in the SE wall
 - around NW windows
- traditional artificial hydraulic lime mortar
- common emulsion paint (interior + exterior)





2 - Alhos-Vedros tide-mill

History

- built beginning of the XVIII century
- inactive since 1940, will work as a museum

Situation

- inside a branch of the Tagus estuary
- less than 10 km from the open sea

Materials (1999):

- plasters were replaced up to:
 - 2.6m in the NW wall
 - 1.4m in the SW wall
 - 1.0m in the SE wall
 - around NW windows
- traditional artificial hydraulic lime mortar
- common emulsion paint

Damage (2002):

- efflorescence, peeling of the paint, sanding of the plaster – in the interior
- affects mostly the (new) plaster

2 - Alhos-Vedros tide-mill

XDR on efflorescence (NW wall)

Termonatrite ($\text{Na}_2\text{CO}_3 \cdot \text{H}_2\text{O}$)	+
Gaylussite, $\text{Na}_2\text{Ca}(\text{CO}_3)_2 \cdot 5\text{H}_2\text{O}$	+
Trona ($\text{Na}_2\text{H}(\text{CO}_3)_2 \cdot 2\text{H}_2\text{O}$)	+
Halite (NaCl)	+
Calcium hydroxide ($\text{Ca}(\text{OH})_2$)	+
Calcite, CaCO_3	+
Quartz, SiO_2	++
Feldspars / mica / caulinite	+



XRD

2 - Alhos-Vedros tide-mill

Termonatrite ($\text{Na}_2\text{CO}_3 \cdot \text{H}_2\text{O}$)

Gaylussite, $\text{Na}_2\text{Ca}(\text{CO}_3)_2 \cdot 5\text{H}_2\text{O}$

Trona ($\text{Na}_2\text{H}(\text{CO}_3)_2 \cdot 2\text{H}_2\text{O}$)

Halite (NaCl)



XRD

2 - Alhos-Vedros tide-mill

Termonatrite ($\text{Na}_2\text{CO}_3 \cdot \text{H}_2\text{O}$)

Gaylussite, $\text{Na}_2\text{Ca}(\text{CO}_3)_2 \cdot 5\text{H}_2\text{O}$


Trona ($\text{Na}_2\text{H}(\text{CO}_3)_2 \cdot 2\text{H}_2\text{O}$)

Halite (NaCl)

- sodium chloride:
 - probably carried by some capillary rising moisture or by salt mist
- efflorescence mainly composed of alkali-carbonate salts:
 - derive probably from the plaster (artificial hydraulic lime...)



XRD



2.7 m →




2.0 m →




1.5 m →

1.0 m →

0.5 m →

0.15 m →





the MC is low inside the wall:

=> rising damp is not the main problem, despite the direct contact of the mill foundations with the river water

2 - Alhos-Vedros tide-mill

Where does the water come from?

2 - Alhos-Vedros tide-mill

Where does the water come from?
circumstantial evidence ...

2 - Alhos-Vedros tide-mill

Where does the water come from?
circumstantial evidence ...



Salt damage:

- close to the pavement

2 - Alhos-Vedros tide-mill

Where does the water come from?
circumstantial evidence ...



Salt damage:

- close to the pavement
- around the NW windows



2 - Alhos-Vedros tide-mill

Where does the water come from?
circumstantial evidence ...



Salt damage:

- close to the pavement
- around the NW windows
- more intense on the NW wall than on the SE wall

Damage intensity





2 - Alhos-Vedros tide-mill

Where does the water come from?
circumstantial evidence ...



Salt damage:

- close to the pavement
- around the NW windows
- more intense on the NW wall than on the SE wall
- NW wall: increases towards the N corner

Damage intensity



Hypothesis: damage occurs on colder surfaces
where condensation hazard is higher

2 - Alhos-Vedros tide-mill

Where does the water come from?
circumstantial evidence ...



Cold /wet day

Sun suddenly appeared

Air temp raised rapidly

Wet spots start
appearing
(condensation...)

November 2002

2 - Alhos-Vedros tide-mill

Conclusions

- Rising damp is not very significant
- Moisture source: probably dew point condensation

2 - Alhos-Vedros tide-mill

Conclusions

- Rising damp is not very significant
- Moisture source: probably dew point condensation
- Salts: alkali carbonate + some sodium chloride (sea)
- Damage affects mostly the (new) hydraulic plaster

2 - Alhos-Vedros tide-mill

Conclusions

- Rising damp is not very significant
- Moisture source: probably dew point condensation
- Salts: alkali carbonate + some sodium chloride (sea)
- Damage affects mostly the (new) hydraulic plaster

... the main reason for the observed decay seems to lay in the plaster itself:

2 - Alhos-Vedros tide-mill

Conclusions

- Rising damp is not very significant
- Moisture source: probably dew point condensation
- Salts: alkali carbonate + some sodium chloride (sea)
- Damage affects mostly the (new) hydraulic plaster

... the main reason for the observed decay seems to lay in the plaster itself:

Key recommendations

2 - Alhos-Vedros tide-mill

Conclusions

- Rising damp is not very significant
- Moisture source: probably dew point condensation
- Salts: alkali carbonate + some sodium chloride (sea)
- Damage affects mostly the (new) hydraulic plaster

... the main reason for the observed decay seems to lay in the plaster itself:

Key recommendations

- Prevent the a access of chloride => hardly feasible ...

2 - Alhos-Vedros tide-mill

Conclusions

- Rising damp is not very significant
- Moisture source: probably dew point condensation
- Salts: alkali carbonate + some sodium chloride (sea)
- Damage affects mostly the (new) hydraulic plaster

... the main reason for the observed decay seems to lay in the plaster itself:

Key recommendations

- Prevent the a access of chloride => hardly feasible ...
- ⇒ try test plaster of low alkali content (prevents formation of alkali carbonate salts)

2 - Alhos-Vedros tide-mill

Conclusions

- Rising damp is not very significant
- Moisture source: probably dew point condensation
- Salts: alkali carbonate + some sodium chloride (sea)
- Damage affects mostly the (new) hydraulic plaster

... the main reason for the observed decay seems to lay in the plaster itself:

Key recommendations

- Prevent the access of chloride => hardly feasible ...
=> **try test plaster of low alkali content** (prevents formation of alkali carbonate salts)
- will work as a museum => surface free of damage => salt accumulating plaster

3 - House of Despacho



3 - House of Despacho



3 - House of Despacho

History

- built early XVIII century
- used as sacristy and mortuary chapel




3 - House of Despacho

History

- built early XVIII century
- used as sacristy and mortuary chapel

Situation

- next to the Mondego (river)
- 20 km from the Atlantic





3 - House of Despacho

History

- built early XVIII century
- used as sacristy and mortuary chapel

Situation

- next to the Mondego (river)
- 20 km from the Atlantic

Materials

- 2001:
 - new lime-sand plasters and renders
 - cement-based adhesion coat

3 - House of Despacho

History

- built early XVIII century
- used as sacristy and mortuary chapel

Situation

- next to the Mondego (river)
- 20 km from the Atlantic

Materials

- 2001:
 - new lime-sand plasters and renders
 - cement-based adhesion coat
- a flood (rupture in Mondego dikes) submerged the church up to 2.5 m



<http://emiliotorrao.blogspot.pt/2011/02/montemor-o-velho-pode-conhecer-novas.html>

3 - House of Despacho

History

- built early XVIII century
- used as sacristy and mortuary chapel

Situation

- next to the Mondego (river)
- 20 km from the Atlantic

Materials

- 2001:
 - new lime-sand plasters and renders
 - cement-based adhesion coat
- a flood (rupture in Mondego dikes) submerged the church up to 2.5 m
- 2003:
 - commercial potassium-silicate paint (with hydrofuge additives) applied at the interior and exterior



<http://emiliotorrao.blogspot.pt/2011/02/montemor-o-velho-pode-conhecer-novas.html>



3 - House of Despacho

History

- built early XVIII century
- used as sacristy and mortuary chapel

Situation

- next to the Mondego (river)
- 20 km from the Atlantic

Materials

- 2001:
 - new lime-sand plasters and renders
 - cement-based adhesion coat
- a flood (rupture in Mondego dikes) submerged the church up to 2.5 m
- 2003:
 - commercial potassium-silicate paint (with hydrofuge additives) applied at the interior and exterior

Damage (2003)



- few months after the works ended...
- affects 50% of the plastered area
- cracking + efflorescence
- affects upper part of walls (1.0/1.5 - 2.7 m)




Evolution of damage:




- 1) efflorescence develops at the interface plaster/paint
- 2) the crystals push the paint layer and cause its rupture
- 3) long needle-like crystals appear + sanding of the plaster

plaster cracks = critical points where the degradation first starts and develops faster










Significant amount of moisture exists inside the walls


3 - House of Despacho




3 - House of Despacho

XDR on efflorescence

Crystalline compounds	Sampling height (m)			
	1.1	1.5	2.1	2.6
Hydrous sodium carbonate, $\text{Na}_2\text{CO}_3 \cdot 7\text{H}_2\text{O}$	++	+	-	-
Natron, $\text{Na}_2\text{CO}_3 \cdot 10\text{H}_2\text{O}$	+	++	-	-
Gaylussite, $\text{Na}_2\text{Ca}(\text{CO}_3)_2 \cdot 5\text{H}_2\text{O}$	-	+	+	++
Quartz, SiO_2	-	-	vtg	-
Cristobalite, SiO_2	?	?	+	+
Calcite, CaCO_3	+	+	++	+ / ++
Rutile, TiO_2	+	+	++	++



3 - House of Despacho



Hydrous sodium carbonate,
 $\text{Na}_2\text{CO}_3 \cdot 7\text{H}_2\text{O}$

Natron, $\text{Na}_2\text{CO}_3 \cdot 10\text{H}_2\text{O}$

Gaylussite, $\text{Na}_2\text{Ca}(\text{CO}_3)_2 \cdot 5\text{H}_2\text{O}$

3 - House of Despacho

Conclusions

3 - House of Despacho

Conclusions

High moisture content inside the walls

3 - House of Despacho

Conclusions

High moisture content inside the walls:

- rising damp?
- accumulation during the flood?

3 - House of Despacho

Conclusions

High moisture content inside the walls:

- rising damp?
- accumulation during the flood?

=> repeat MC/HMC measurements => know evolution...

3 - House of Despacho

Conclusions

High moisture content inside the walls:

- rising damp?
- accumulation during the flood?

=> repeat MC/HMC measurements => know evolution...

Key recommendations

3 - House of Despacho

Conclusions

High moisture content inside the walls:

- rising damp?
- accumulation during the flood?

=> repeat MC/HMC measurements => know evolution...

Key recommendations

- plaster of low alkali content (no cement-based adhesion layer...)

3 - House of Despacho

Conclusions

High moisture content inside the walls:

- rising damp?
- accumulation during the flood?

=> repeat MC/HMC measurements => know evolution...

Key recommendations

- plaster of low alkali content (no cement-based adhesion layer...)
- do not use hydrophobic paint
 - hydrophobic surface layer => lower evaporation rate (stage II conditions)
 - subflorescence disrupts the paint layer (rather, let the salt go out...)

4 - Sta Clara Monastery

4 - Sta Clara Monastery



4 - Sta Clara Monastery



- located in Coimbra (20 km from the coast)
- study: ground floor of the cloister gallery
- built in the first half of the XVIII century



4 - Sta Clara Monastery



- located in Coimbra (20 km from the coast)
- study: ground floor of the cloister gallery
- built in the first half of the XVIII century
- traditional cement plaster + acrylic emulsion paint
- applied in 1987





4 - Sta Clara Monastery

Damage:

- either upper on the walls, next to stone elements

4 - Sta Clara Monastery

Damage:

- either upper on the walls, next to stone elements
- or close to the pavement



Damage close to the pavement



XDR on sanded surface material (NE wall)

Damage close to the pavement



XDR on sanded surface material (NE wall)

Damage up on the wall



Damage close to the pavement



XDR on sanded surface material (NE wall)

Damage up on the wall



XDR on efflorescence (NW wall)

Damage close to the pavement



Damage up on the wall



XDR on sanded surface material (NE wall)

Trona, $\text{Na}_3\text{H}(\text{CO}_3)_2 \cdot 2\text{H}_2\text{O}$?/vtg
Gaylussite, $\text{Na}_2\text{Ca}(\text{CO}_3)_2 \cdot 5\text{H}_2\text{O}$	+
Niter, KNO_3	?/vtg
Calcite, CaCO_3	+++
Dolomite, $\text{CaMg}(\text{CO}_3)_2$	+
Quartz, SiO_2	+

XDR on efflorescence (NW wall)

Trona, $\text{Na}_3\text{H}(\text{CO}_3)_2 \cdot 2\text{H}_2\text{O}$	++/+++
Gaylussite, $\text{Na}_2\text{Ca}(\text{CO}_3)_2 \cdot 5\text{H}_2\text{O}$	-
Niter, KNO_3	-
Calcite, CaCO_3	++/+++
Dolomite, $\text{CaMg}(\text{CO}_3)_2$	-
Quartz, SiO_2	vtg

Damage close to the pavement



Damage up on the wall









Trona, $\text{Na}_3\text{H}(\text{CO}_3)_2 \cdot 2\text{H}_2\text{O}$

Gaylussite, $\text{Na}_2\text{Ca}(\text{CO}_3)_2 \cdot 5\text{H}_2\text{O}$




Niter, KNO_3

Trona, $\text{Na}_3\text{H}(\text{CO}_3)_2 \cdot 2\text{H}_2\text{O}$





- Rising damp seems limited (< 5% inside)
 - In-depth MC/HMC profile at the level of maximum damage => MC decreases towards the interior of the wall (at the deepest points, MC ≈ HMC)
- => superficial source of liquid moisture is likely



- Rising damp seems low also here
- In-depth MC/HMC at the bottom of the wall => MC decreases towards the interior of the wall (at the deepest point, the MC is lower than the HMC)

=> superficial source of liquid moisture is likely also here



February 2004



January 2004

Possible moisture sources



February 2004



January 2004

Possible moisture sources

Soil surface water (cloister garden)?

Hygroscopic water (stone) ?

Condensation (mainly on the stone) ?

4 - Sta Clara Monastery

Conclusions

4 - Sta Clara Monastery

Conclusions

Moisture source? **superficial source is likely ...**

4 - Sta Clara Monastery

Conclusions

Moisture source? **superficial source is likely ...**

- rising damp is low => soil surface water (cloister garden)?

4 - Sta Clara Monastery

Conclusions

Moisture source? **superficial source is likely ...**

- rising damp is low => soil surface water (cloister garden)?
- hygroscopic water (stone) ?
- condensation (mainly on the stone) ?

4 - Sta Clara Monastery

Conclusions

Moisture source? **superficial source is likely ...**

- rising damp is low => soil surface water (cloister garden)?
- hygroscopic water (stone) ?
- condensation (mainly on the stone) ?

Salts = carbonate (plaster) + nitrate close to the pavement (some rising damp)

4 - Sta Clara Monastery

Conclusions

Moisture source? **superficial source is likely ...**

- rising damp is low => soil surface water (cloister garden)?
- hygroscopic water (stone) ?
- condensation (mainly on the stone) ?

Salts = carbonate (plaster) + nitrate close to the pavement (some rising damp)

Key recommendations

4 - Sta Clara Monastery

Conclusions

Moisture source? **superficial source is likely ...**

- rising damp is low => soil surface water (cloister garden)?
- hygroscopic water (stone) ?
- condensation (mainly on the stone) ?

Salts = carbonate (plaster) + nitrate close to the pavement (some rising damp)

Key recommendations

- correct drainage of rain water in the cloister garden
- analyse the stone (**hygroscopic features ... salts? => dessalination?**)
- **plaster of low alkali content**

Inspection form

Inspection form

FICHA DE INSPEÇÃO DE OBRA

INFORMAÇÃO GERAL		
Data e hora de visita:	Técnicos presentes:	Condições meteorológicas:
Nome do edifício:		Alcova/localidade:
Entidade responsável:		Interesse patrimonial (classificação):
Descrição genérica:		
Uso (atual e anterior):		
<ul style="list-style-type: none"> - Ocupação em geral/interior? - Equipamento - Limpeza/estado geral/objetos - Outros elementos, portas, etc. 		
Volumetria e orientação:		
<ul style="list-style-type: none"> - Área (superfície) - Nº de pisos - Direção: em planta - Nº de janelas - Paredes 		
Ambiente envolvente:		
<ul style="list-style-type: none"> - Zona costeira / interior - Zona urbana / rural / industrial - Características geológicas 		
Tipologia construtiva (incluindo revestimentos):		
<ul style="list-style-type: none"> - Fundação - Paredes - Pisos - Coberturas - Calhandrias 		
Estado geral de conservação:	Ambiente - Exterior: <ul style="list-style-type: none"> - Coberturas - Paredes - Vãos 	
	Estrutura: <ul style="list-style-type: none"> - Interior: <ul style="list-style-type: none"> - Paredes - Paredes - Tectos 	
Fases de construção e datas:		
Detecção de avarias relevantes (cracks, infiltrações, deslocamentos, deteriorações, etc.) e datas:		
Intervenções construtivas passadas, presentes ou futuras (casos que sejam relevantes):		
<ul style="list-style-type: none"> - Data - Objectos - Elementos interveniêntes - Soluções utilizadas - Implicações para o usuário 		
Observações:		

FICHA DE INSPEÇÃO DE OBRA

ANOMALIAS
Tipo de degradação (terminologia Duragrafias):
Elementos afectados (determinar estado dos revestimentos): <ul style="list-style-type: none"> - Fachada ou paredes / interiores - Paredes exteriores ou interiores - Paredes revestidas, cores - Zonas fónicas - Paredes / tectos
Tipologia construtiva e constituição dos elementos afectados: <ul style="list-style-type: none"> - Tipo de alvenaria, reboco, gesso - Pisos e/ou impermeabilização / encanamentos - Cota de captação na base das paredes?
Extensão (Nº de áreas total dos elementos afectados) e profundidade (mm) da degradação:
Localização das anomalias degradadas: <ul style="list-style-type: none"> - Face exposta / degradação exterior - Piso/parede / alvenaria / outro tipo - Base da parede / topo / outra zona - Junta entre os vários elementos? - Situação relativa sobre o tipo e altura / orientação? - Orientação das paredes degradadas
Matéria da anomalia - Infiltração (pedra, etc): <ul style="list-style-type: none"> - Paredes: estado tipo e data? - Condição observada em detalhe (tipo de avaria) - Tipo de avaria? - Degradação da estrutura? - Medidas tomadas (limpeza, pintura, aplicação, etc)
Colheita de amostras - Data e identificação das amostras: <ul style="list-style-type: none"> - Localização (altura - largura) - Profundidade - Dimensão - Espessura do elemento (paredes) - Medidas constantes
Testes realizados e resultados: <ul style="list-style-type: none"> - HR e temperatura - Penetração / sonar - etc.
Hipótese (diagnóstico):
Observações (condições particulares de exposição, presença de libertação, etc):

GENERAL INFORMATION

Inspection

- date / time
- weather conditions
- performed by

Identification of the building

- building name / address / location
- responsible entity / owner
- heritage interest / classification

Use(s) of the building (current and previous)

- Use(s)
- Heating
- Storage of salted goods
- Domestic animals, pigeons, etc.

Building dimensions and orientation

- plan / diagram (indicate North)
- dimensions
- different floors / bodies

Surrounding environment

- coastal / interior
- urban / rural / industrial
- particular features ...

Constructive typology (materials + functions)

- structure
- foundations
- walls (ex: cavity walls? filled with what?)
- doors/windows
- roof
- pavements
- surrounding terrain / pavement - impermeable or diverting rain water to the base of the walls?

Water supply / drainage systems

location of the pipes + state of conservation

Perceived ventilation

Construction

phases and dates

State of conservation

envelope, structure, interiors

Events / disasters

floods, fires, partial collapses, landslides, demolitions, etc. - dates

Past, present or planned interventions

dates, objectives

elements addressed, constructive solutions
contractor / restorer

ANOMALIES

Type of degradation

describe (may use some classification, but also describe with your own words + fotos)

Elements affected

facades / internal coverings
exterior / interior walls
semi-buried walls, basements
other...

Typology of the affected elements

type of masonry, plaster/render, paint
damp proof courses?

Extension of the damage

area (% of the total area)
depth

Degraded areas

disperse spots / extensive degradation
ground floor / high floor
wall base / top / middle height of the wall
next to specific elements
exposition of the affected walls (N, S, W, E)

History of the anomaly

who provided this information
early signs (type and date)
systematic occurrence at certain time of the year?
how long after the works?
evolution of the damage => **several observations or indirect information from users (specify):**

- **winter / summer**
- **rain / dry weather**

measures taken (cleaning, repairs, etc.)

Sampling

clear identification of the samples
purpose (tests to carry out)
location (+ foto)
depth
dimensions
thickness of the element (wall)
constituent materials

Site tests / quantitative data

RH / air temp / solar radiation (at least qualitatively)
percussion: hollow sound => detached layers

Hypothesis (diagnosis)

Case-studies in plastering and rendering mortars. Sampling and testing for salts

Thank you